







Bayview Street

- 26 New trees in vacant sites
- 42 Trees to be retained
- 13 Low value trees (potential to replace)
- 52 Trees to be replaced
- 133 Total trees in street

Section 1

-  Vacant suitable site
-  Retain tree
-  Low value tree (potential to remove)
-  Remove and replace tree



Section 2



Vacant suitable site




Retain tree







Low value tree (potential to remove)




Remove and replace tree







Section 3

-  Vacant suitable site
-  Retain tree
-  Low value tree (potential to remove)
-  Remove and replace tree



Section 4

-  Vacant suitable site
-  Retain tree
-  Low value tree (potential to remove)
-  Remove and replace tree



Section 5



Vacant suitable site



Retain tree







Low value tree (potential to remove)



Remove and replace tree



Section 6

-  Vacant suitable site
-  Retain tree
-  Low value tree (potential to remove)
-  Remove and replace tree

